

Notification of cabinetisation under clause 38.11.2 (C) of the UCLL general terms; "It is necessary to replace the relevant part of the Local Loop Network because it has come to the end of its life, has significantly deteriorated, or has been damaged beyond repair ..."

Exchange	Blenheim
Exchange code	BM
Existing cabinet (if relevant)	BM/09
Cabinet Location	Corner of Lewis and Scott St NZMG reference <ul style="list-style-type: none"> • X Coordinate 2589911 • Y Coordinate 5963973
Work proposed	To advance by 3 months the installation of the BM/09 cabinet, a double bay Whisper cabinet complete with Voice Mux and a DSLAM, to allow the abandonment of the copper feeder serving the area. Proposal is to cutover the cabinet July 2010
Reasons why work required	The area served by the proposed cabinet is currently fed by a lead sheath feeder cable which is being affected by severe corrosion resulting in a loss of air pressure and the imminent possibility of loss of service due to water ingress. This cabinet is currently timed for cutover in the period October to December 2010 and the proposal is to advance this to July 2010. Action is required to replace this cable before total failure of service occurs.
Cabinet space for Access Seeker's equipment	Space availability will be subject to the terms of the Sub-loop UCLL STD.
Proposed method of voice and data provisioning	Voice services will be provided by VMUX from the cabinet. Broadband services will be provided by an ISAM delivering ADSL 2+ services.
Expected broadband performance	With the installation of the proposed cabinet all customers will be in range to receive 10Mbps or better service from an ADSL2+ DSLAM
Number of all customers affected	Total MPFs affected = 320 Total customers affected = 320
Availability of services over the remaining feeder copper	The feeder cable will not be retained due to its condition

