

CABINETISATION NOTICE

This Cabinetisation Notice constitutes notification of cabinetisation under clause 38.11.2(c) of the UCLL and UCLL Co-location Standard Terms Determination General Terms: "...it is necessary to replace the relevant part of the Local Loop Network because it has come to the end of its life, has significantly deteriorated, or has been damaged beyond repair .."

Exchange	Riccarton
Exchange code	RIC
Existing cabinet (if relevant)	RIC/Z
Cabinet Location	133 Yaldhurst Rd NZMG reference <ul style="list-style-type: none"> • X Coordinate 2474215 • Y Coordinate 5742095
Exchange Unbundled or forecasted to be	Yes
Cabinet Area Classification	NGN Zone 1
Work proposed	Establish a double bay Whisper cabinet to replace the existing copper fed cabinet. Originally this cabinet was planned as a single bay Whisper in Period 11, 1/01/2011. Note that the final cabinet service area will actually consolidate the existing RIC/Z and the RIC/AC cabinet service areas.
Reasons why work required	The copper feeder cable has become a maintenance liability and the new cabinet will be advanced one quarter to P10, 1/10/2010 to reduce the risk of customer service outages.
Cabinet space for Access Seeker's equipment	A double bay Whisper cabinet is being installed. Space availability will be subject to the terms of the Sub-loop UCLL STD.
Proposed method of voice and data provisioning	Voice services will be provided by VMUX from the cabinet. Broadband services will be provided by an ISAM delivering ADSL 2+ services.
Expected broadband performance	The driver is a faulty feeder cable, at this cabinet the feeder is 3,142m from the exchange
Number of all customers affected	Total MPFs affected = 110
Number of all waiters / number of Access Seeker's waiters in the affected area	No waiters, this project is not for growth
Availability of services over the remaining feeder copper	SLER will not be available